


[BMW F48 X1 xDrive18d SAV](#) / [Repair Manuals and Technical Data](#) / [51 Body equipment](#) / [51 43 Side Trim Panel with Armrests](#) /

51 47 000 Removing and installing/replacing front (inside) left or right door sill cover strip



Special tools required:


- [00 9 325](#)




Attention!

Do not raise door sill cover strip (1) over entire length simultaneously.

Unclip rear door sill cover strip (1) from clips (2) starting from the rear with special tool [00 9 325](#).



If necessary lift clip (1) from floor panel (2) and clip on door sill cover strip.

**Installation note:**

Replace defective clips (1) on door sill cover strip (2).

For informational purposes only. The information on this website is provided AS-IS with no warranties, express or implied, and is not guaranteed to be error-free, up-to-date or complete. NewTIS and BMW assume no liability for any loss or damage arising from the use or reliance on the information and content on this website. The content on this website is subject to change without notice.