

[BMW F48 X1 xDrive18d SAV / Repair Manuals and Technical Data / 51 Body equipment / 51 47 Floor/luggage compartment/engine compartment, trim panel /](#)

51 46 050 Removing and installing/replacing top cover on tail panel




Necessary preliminary tasks:

- Removing [luggage compartment well](#)



Removal:




Release expanding rivets (1) from tail panel trim (2).

Lift off trim on tail panel (2).



Installation:



Install trim on tail panel (2).

Mount expanding rivets (1) on tail panel trim (2).



Required follow-up work:

- Install [luggage compartment well](#)

For informational purposes only. The information on this website is provided AS-IS with no warranties, express or implied, and is not guaranteed to be error-free, up-to-date or complete. NewTIS and BMW assume no liability for any loss or damage arising from the use or reliance on the information and content on this website. The content on this website is subject to change without notice.